Make	FORD	
Model	FOCUS 2.0 ECOBOOST ST1	
Vin	WF05XXGCC5HK213	308
Engine Specifications	2.0	Petrol
Vehicle Type	H/B	
Service Plan	N/A	

Year	2018
Km	109183
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	<b>—</b>

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		109183 Km	Dip Stick	No Visible Leaks	•
Oil Filter	Renewed		Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Not Applicable	lacksquare	Fan Belt	No Fault Code	•
Air Filter	Within Specification	lacksquare	Fan belt Tensioner	Good Condition	•
Cabin Filter	Within Specification	<b>—</b>	Alternator Belt	No Fault Code	•
Spark Plugs	Within Specification	lacksquare	Power Steering Belt	No Fault Code	•
Brake Fluid	Within Specification	_	Aircon Belt	No Fault Code	<b>~</b>
Antifreeze	Within Specification	<b>—</b>	Multi V belt	No Fault Code	<b>~</b>
Rear Main Seal	No Visible Leaks		Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	No Visible Leaks	
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	-
Thermostat	No Visible Leaks	
Aircon Gas	Good Condition	
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	<b>V</b>
Turbo	Good Condition	•
Injectors	Good Condition	lacksquare
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>~</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	<b>—</b>
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	lacksquare
CV Joints	Good Condition	•
CV Boots	Good Condition	lacksquare
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	▼
Wheel Bearings	Good Condition	▼
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	Good Condition	<b>V</b>
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	<b>V</b>
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Good Condition	<b>~</b>

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Not Applicable	
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	<b>T</b>

Ignition System		
Diagnostics	No Fault Code	<b>—</b>
Cyl Leakage Test	Good Condition	<b>—</b>
Road Test	Good Condition	<b>~</b>
Handling	Good Condition	•

Concluding Remarks		

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
HENDRIE	30-May-2024



