

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:johan@boschgezina.co.za

Sn:988579800333

Time:2024-09-30 13:30:24

Technician Name:john

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2022

Make:KIA

Model:K2500/K2700/K3000/K3

VIN:KNCSHX76LN7590575

Displacement:D 2.5 TCI-A2

Odometer:53503 miles

Vehicle Software Version:V10.50

## Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.CODE(Transmitter Code Saving)