Make	MAZDA	
Model	CX-5 2.0 DYNAMIC A/T	
Vin	JM6KF2W7AJ014928	5
Engine Specifications	2.0	Petrol
		1 01.01
Vehicle Type	SUV	1 51151

Year	2018
Km	113297
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	<b>—</b>	Aircon Controls	Good Condition	<b>T</b>
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition	•
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	-	Alternator Belt	Good Condition	•
Spark Plugs	Good Condition	•	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	-	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	<b>~</b>	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	-	Engine Mountings	Good Condition	•
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	100%	_
Front Brake Discs	Good Condition	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	•
Rear Brake Discs	Good Condition	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	_
Rear Linings	-Select-	•
Brake Master	Good Condition	_
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	<b>-</b>
Throttle	Good Condition	•
Turbo	Good Condition	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	-

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	lacksquare
Distrubutor	Not Applicable	_
HT Leads	Not Applicable	lacksquare



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	<b>—</b>
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	
CV Joints	Good Condition	•
CV Boots	Good Condition	
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	
Shocks Rear	Good Condition	lacksquare
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	lacksquare
Control Arms	Good Condition	•
Sideshafts/Seal	Good Condition	•
Propshaft	Good Condition	
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	Good Condition	•
Gear Selector	Good Condition	<b>—</b>
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Not Applicable	-
Cyl Leakage Test	Not Applicable	-
Road Test	Not Applicable	-
Handling	Not Applicable	•

Bosch Technician	General Comments
-Select-	
NEW Technician	Date of Inspection
SHAUN OLIVIER	



**Concluding Remarks** 

