Make	VOLKSWAGEN	
Model	CADDY4 1.6i (81KW) F/C P/V	
Vin	WV1ZZZ2KZKX127276	
Engine Specifications	1.6 Per	trol
Vehicle Type	P/V	
Service Plan	N/A	

Year	2019
Km	135011
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	•
Cluster	Within Specification	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	<b>—</b>
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	lacksquare
Oil Filter	Good Condition		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	No Visible Leaks		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	<b>V</b>
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	No Fault Code		Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks		Aircon Belt	No Cracks	•
Antifreeze	No Visible Leaks		Multi V belt	No Cracks	~
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	<b>V</b>
Sump/Gasket	No Visible Leaks		PCV Valve	No Visible Leaks	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	<b>~</b>
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	•
Throttle	No Fault Code	lacksquare
Turbo	Not Applicable	lacksquare
Injectors	No Fault Code	lacksquare
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>~</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	No Visible Leaks	•
Power Steering Pump	Not Applicable	<b>•</b>
Wheel Alignment	Within Specification	•
CV Joints	No Visible Leaks	<b>•</b>
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	<b>V</b>
Shock Mountings Front	Within Specification	<b>—</b>
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	<b>—</b>
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	<b>—</b>
Wheel Nuts/Studs	Within Specification	<b>—</b>
Tyres & Spare	Within Specification	<b>—</b>
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	No Visible Leaks	•
Clutch Slave	No Visible Leaks	<b>—</b>
Clutch Cable	Not Applicable	<b>T</b>
Gearbox	No Visible Leaks	<b>T</b>
Gear & Diff oil	No Visible Leaks	<b>—</b>
Auto Transmission	Not Applicable	<b>—</b>
Gear Selector	Within Specification	<b>T</b>
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



