

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: citton cars  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: jaco@boschgezina.co.za  
Sn: 988579800333  
Time: 2024-05-13 08:25:32  
Technician Name: Ricardo  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year: 2019  
Make: VW\_CV  
VIN: WV1ZZZ2KZKX127276  
Displacement: G 1.4 MPI  
Odometer: 135010 km  
Vehicle Software Version: V10.23

## Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.03 Brake Electronics
- 3.08 Climate Control Module
- 4.09 Electronic Central Electric
- 5.15 Airbag
- 6.16 Steering Column Electronics Systems
- 7.17 Instrument Cluster
- 8.19 Data Bus OBD Interface
- 9.25 Anti-Theft Immobilizer
- 10.42 Driver's Door Electronics
- 11.44 Power Steering
- 12.52 Passenger's Door Electronics
- 13.56 Radio
- 14.61 Battery Regulation
- 15.69 Trailer Function