Make	FORD	
Model	FOCUS 1.5 ECOBOOST TREND A/T	
Vin	WF04XXGCC4HR03	3187
Engine Specifications	1.5	Petrol
Vehicle Type	S/D	
Service Plan	N/A	

Year	2017
Km	125545
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	~	Aircon Controls	Good Condition	•
Cluster	Good Condition	V	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition		Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	1	25545 Km	Dip Stick	No Visible Leaks	V
Oil Filter	Renewed	•	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Not Applicable	•	Fan Belt	Good Condition	•
Air Filter	Within Specification	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Within Specification	—	Alternator Belt	Good Condition	•
Spark Plugs	Within Specification	•	Power Steering Belt	Good Condition	-
Brake Fluid	Within Specification	•	Aircon Belt	Good Condition	-
Antifreeze	Within Specification	~	Multi V belt	Good Condition	T
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	lacksquare
Front Brake Sensor	Not Applicable	
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	lacksquare
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	lacksquare
Rear Linings	-Select-	lacksquare
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	~
Thermostat	Good Condition	
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	~

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Good Condition	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Renewed	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Renewed	•
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Renewed	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Renewed	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Good Condition	
Auto Transmission	Good Condition	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	T

Ignition System		
Diagnostics	Good Condition	
Cyl Leakage Test	Good Condition	lacksquare
Road Test	Good Condition	~
Handling	Good Condition	~

Concluding Remarks		

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
HENDRIE	05-Jun-2024



