

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 15933

| Make | MERCEDES-BENZ |
|---------------------------------------|--------------------|
| Model | CLA220d AMG A/T |
| Vin | WDD1173032N459515 |
| | |
| Engine Specifications | Diesel |
| Engine Specifications Vehicle Type | Diesel S /D |

| Year | 2017 |
|---------------|-------------------|
| Km | 114109 |
| Transmission | Automatic |
| Colour | SILVER |
| Branch | Bosch Car Service |
| Warranty Plan | N/A |

| Interior | | | | | |
|-----------------------|----------------|---|------------------|----------------|---|
| Radio / Entertainment | Good Condition | • | Aircon Controls | Good Condition | • |
| Cluster | Good Condition | • | Electric Windows | Good Condition | • |
| | | | | | |

| Exterior | | | | | |
|-------------------------|----------------|---|--------------|----------------|---|
| Windscreen | Good Condition | • | Mag Wheels | Good Condition | • |
| Side Mirrors / Electric | Good Condition | • | Wiper Blades | Good Condition | • |

BOSCH VEHICLE INSPECTION

| Oil Service | | Km | Dip Stick | Good Condition | - |
|--------------------|----------------|----|---------------------|----------------|---|
| Oil Filter | Good Condition | • | Oil Filler Cap | Good Condition | • |
| Fuel/Diesel Filter | Good Condition | - | Fan Belt | Good Condition | - |
| Air Filter | Good Condition | - | Fan belt Tensioner | Good Condition | - |
| Cabin Filter | Good Condition | - | Alternator Belt | Good Condition | - |
| Spark Plugs | Not Applicable | - | Power Steering Belt | Good Condition | • |
| Brake Fluid | Good Condition | • | Aircon Belt | Good Condition | • |
| Antifreeze | Good Condition | - | Multi V belt | Good Condition | • |
| Rear Main Seal | Good Condition | - | Engine Mountings | Good Condition | • |
| Sump/Gasket | Good Condition | - | PCV Valve | Good Condition | - |
| | | | | | |



| Braking System | | |
|--------------------|----------------|---|
| Front Brake Pads | 80% | • |
| Front Brake Discs | Good Condition | • |
| Front Brake Sensor | Good Condition | • |
| Rear Brake Pads | 60% | • |
| Rear Brake Discs | Good Condition | • |
| Rear Brake Sensor | Good Condition | • |
| Rear Drums | Not Applicable | • |
| Rear Linings | -Select- | • |
| Brake Master | Good Condition | • |
| Hand Brake | Good Condition | • |
| Brake Calipers | Good Condition | • |
| Brake Hose | Good Condition | • |

| Cooling System | | |
|-------------------|----------------|---|
| Radiator | Good Condition | • |
| Radiator Hoses | Good Condition | • |
| Waterpump | Good Condition | • |
| Thermostat | Good Condition | • |
| Aircon Gas | Good Condition | • |
| Aircon Pump | Good Condition | • |
| Aircon Condensor | Good Condition | • |
| Interior Fan | Good Condition | • |
| Interior Radiator | Good Condition | • |

| Fueling System | | |
|-----------------|----------------|---|
| Intake Manifold | Good Condition | - |
| Throttle | Good Condition | - |
| Turbo | Good Condition | - |
| Injectors | Good Condition | • |
| Fuel Pump | Good Condition | • |
| Fuel Lines | Good Condition | • |

| Ignition System | | |
|-----------------|----------------|---|
| Ignition Coils | Not Applicable | - |
| Glow Plugs | Good Condition | • |
| Distrubutor | Not Applicable | - |
| HT Leads | Not Applicable | • |



BOSCH INSPECTION REPORT

| Steering & Suspension | | |
|-----------------------|----------------|---|
| Steering Rack | Good Condition | • |
| Power Steering Pump | Good Condition | • |
| Wheel Alignment | Good Condition | • |
| CV Joints | Good Condition | • |
| CV Boots | Good Condition | • |
| Shocks Front | Good Condition | - |
| Shock Mountings Front | Good Condition | - |
| Shocks Rear | Good Condition | • |
| Stabilizer Links | Good Condition | • |
| Wheel Bearings | Good Condition | - |
| Bearing Hubs | Good Condition | • |
| Control Arms | Good Condition | - |
| Sideshafts/Seal | Good Condition | • |
| Propshaft | Not Applicable | • |
| Wheel Nuts/Studs | Good Condition | • |
| Tyres & Spare | Good Condition | • |
| Mag Wheels/Hub Caps | Good Condition | • |

| Transmission & Clutch | | |
|-----------------------|----------------|---|
| Clutch Kit | Not Applicable | • |
| Clutch Master | Not Applicable | • |
| Clutch Slave | Not Applicable | • |
| Clutch Cable | Not Applicable | - |
| Gearbox | Not Applicable | - |
| Gear & Diff oil | Not Applicable | - |
| Auto Transmission | Good Condition | - |
| Gear Selector | Good Condition | • |
| Gear Linkages | Good Condition | • |

| Ignition System | | |
|------------------|----------------|---|
| Diagnostics | Good Condition | • |
| Cyl Leakage Test | Good Condition | • |
| Road Test | Good Condition | • |
| Handling | Good Condition | • |

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

General Comments

Date of Inspection



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

