Make	MAHINDRA	
Model	XUV 500 2.2D MHAWK (W4) 7 SEAT	
Vin	MA1YV2HKUL6077711	
Engine Specifications	2.2	Diesel
Vehicle Type	SUV	
Service Plan	N/A	

Year	2020
Km	68224
Transmission	Automatic
Colour	RED
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	—	Aircon Controls	Good Condition	T
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	—	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition	•
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	-	Alternator Belt	Good Condition	•
Spark Plugs	Good Condition	•	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	-	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	~	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	-	Engine Mountings	Good Condition	•
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Good Condition	lacksquare
Front Brake Sensor	Good Condition	
Rear Brake Pads	100%	•
Rear Brake Discs	Good Condition	
Rear Brake Sensor	Good Condition	•
Rear Drums	-Select-	•
Rear Linings	-Select-	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	—
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	~
Throttle	Good Condition	—
Turbo	Good Condition	—
Injectors	Good Condition	~
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	~

Ignition System		
Ignition Coils	-Select-	•
Glow Plugs	Good Condition	•
Distrubutor	-Select-	•
HT Leads	-Select-	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	T
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	~
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	Good Condition	•
Propshaft	Not Applicable	T
Wheel Nuts/Studs	Good Condition	T
Tyres & Spare	Good Condition	—
Mag Wheels/Hub Caps	Good Condition	V

Transmission & Clutch		
Clutch Kit	Good Condition	—
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	\
Clutch Cable	Not Applicable	T
Gearbox	Good Condition	T
Gear & Diff oil	-Select-	—
Auto Transmission	-Select-	—
Gear Selector	Good Condition	—
Gear Linkages	Good Condition	—

Ignition System		
Diagnostics	-Select-	—
Cyl Leakage Test	-Select-	~
Road Test	-Select-	~
Handling	-Select-	~

Concluding Remarks		

Bosch Technician		General Comments
-Select-	_	

NEW Technician	Date of Inspection
SHAUN OLVIER	17-May-2024



