

BOSCH INSPECTION REPORT

JOB CARD NUMBER 13468

Make	ISUZU		
Model	D-MAX 250 HO X-RIDER A/T E/CAB P/U		
Vin	ACVPREHR2L406041	0	
Engine Specifications	2.5	Diesel	
Vehicle Type	S/C		
Service Plan	N/A		

Year	2021
Km	112734
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION

Engine					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition	-
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition	-
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	•	Alternator Belt	Good Condition	-
Spark Plugs	Not Applicable	-	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	•	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	-	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	•	Engine Mountings	Good Condition	-
Sump/Gasket	Good Condition	-	PCV Valve	Good Condition	-



Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Good Condition	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Good Condition	•
Rear Linings	100%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•

Brake Hose

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	-
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Good Condition	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Good Condition

•

Ignition System		
Ignition Coils	Not Applicable	-
Glow Plugs	Good Condition	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

JOB CARD NUMBER 13468

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	•
CV Joints	Not Applicable	•
CV Boots	Not Applicable	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	Good Condition	•
Propshaft	Good Condition	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	-Select-	-
Clutch Master	-Select-	•
Clutch Slave	-Select-	-
Clutch Cable	-Select-	•
Gearbox	-Select-	
Gear & Diff oil	-Select-	-
Auto Transmission	Good Condition	-
Gear Selector	Good Condition	-
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	-Select-	-
Cyl Leakage Test	-Select-	•
Road Test	-Select-	•
Handling	-Select-	•

Concluding Remarks

Bosch Technician

-Select-

General Comments

Date of Inspection



NEW Technician



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

