












BOSCH INSPECTION REPORT

JOB CARD NUMBER 13806




















Make	TOYOTA		
Model	YARIS 1.5 Xs 5Dr		
Vin	MR2K29F3101166927		
Engine Specifications	1.5	Petrol	<input type="checkbox"/>
Vehicle Type	H/B		
Service Plan	N/A		













Year	2019		
Km	80049		
Transmission	Manual		
Colour	WHITE		
Branch	Bosch Car Service		
Warranty Plan	N/A		










Interior					
Radio / Entertainment	Working Condition			Aircon Controls	Working Condition 
Cluster	Good Condition			Electric Windows	Working Condition 







Exterior					
Windscreen	-Select-			Mag Wheels	Good Condition 
Side Mirrors / Electric	Good Condition			Wiper Blades	Renewed 

BOSCH VEHICLE INSPECTION

Engine					
Oil Service	76750 Km		Dip Stick	Good Condition	
Oil Filter	No Visible Leaks		Oil Filler Cap	No Visible Leaks	
Fuel/Diesel Filter	-Select-		Fan Belt	No Cracks	
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	
Cabin Filter	Within Specification		Alternator Belt	No Cracks	
Spark Plugs	Within Specification		Power Steering Belt	Not Applicable	
Brake Fluid	No Visible Leaks		Aircon Belt	No Cracks	
Antifreeze	No Visible Leaks		Multi V belt	No Cracks	
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	

Braking System		
Front Brake Pads	60%	
Front Brake Discs	Within Specification	
Front Brake Sensor	Not Applicable	
Rear Brake Pads	-Select-	
Rear Brake Discs	Not Applicable	
Rear Brake Sensor	Not Applicable	
Rear Drums	Within Specification	
Rear Linings	40%	
Brake Master	No Visible Leaks	
Hand Brake	Within Specification	
Brake Calipers	Within Specification	
Brake Hose	No Visible Leaks	

Cooling System		
Radiator	No Visible Leaks	
Radiator Hoses	No Visible Leaks	
Waterpump	Within Specification	
Thermostat	Within Specification	
Aircon Gas	No Visible Leaks	
Aircon Pump	Within Specification	
Aircon Condensor	No Visible Leaks	
Interior Fan	Within Specification	
Interior Radiator	No Visible Leaks	

Fueling System		
Intake Manifold	Within Specification	
Throttle	Within Specification	
Turbo	Not Applicable	
Injectors	Within Specification	
Fuel Pump	Within Specification	
Fuel Lines	No Visible Leaks	

Ignition System		
Ignition Coils	No Fault Code	
Glow Plugs	Not Applicable	
Distributor	Not Applicable	
HT Leads	Not Applicable	

Steering & Suspension		
Steering Rack	Within Specification	<input type="checkbox"/>
Power Steering Pump	Not Applicable	<input type="checkbox"/>
Wheel Alignment	Within Specification	<input type="checkbox"/>
CV Joints	Within Specification	<input type="checkbox"/>
CV Boots	No Visible Leaks	<input type="checkbox"/>
Shocks Front	No Visible Leaks	<input type="checkbox"/>
Shock Mountings Front	Within Specification	<input type="checkbox"/>
Shocks Rear	No Visible Leaks	<input type="checkbox"/>
Stabilizer Links	Within Specification	<input type="checkbox"/>
Wheel Bearings	Within Specification	<input type="checkbox"/>
Bearing Hubs	Within Specification	<input type="checkbox"/>
Control Arms	Within Specification	<input type="checkbox"/>
Sideshafts/Seal	No Visible Leaks	<input type="checkbox"/>
Propshaft	Not Applicable	<input type="checkbox"/>
Wheel Nuts/Studs	Within Specification	<input type="checkbox"/>
Tyres & Spare	Within Specification	<input type="checkbox"/>
Mag Wheels/Hub Caps	Within Specification	<input type="checkbox"/>

Transmission & Clutch		
Clutch Kit	Within Specification	<input type="checkbox"/>
Clutch Master	No Visible Leaks	<input type="checkbox"/>
Clutch Slave	No Visible Leaks	<input type="checkbox"/>
Clutch Cable	Not Applicable	<input type="checkbox"/>
Gearbox	Within Specification	<input type="checkbox"/>
Gear & Diff oil	No Visible Leaks	<input type="checkbox"/>
Auto Transmission	Not Applicable	<input type="checkbox"/>
Gear Selector	Good Condition	<input type="checkbox"/>
Gear Linkages	Within Specification	<input type="checkbox"/>

Ignition System		
Diagnostics	No Fault Code	<input type="checkbox"/>
Cyl Leakage Test	No Visible Leaks	<input type="checkbox"/>
Road Test	Within Specification	<input type="checkbox"/>
Handling	Within Specification	<input type="checkbox"/>

Concluding Remarks

Bosch Technician
Raymond Mncube <input type="checkbox"/>

General Comments

NEW Technician

Date of Inspection
03-Jun-2024