

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:2024-06-20 08:00:26

Technician Name:Eugene

Order no:

Service fee:

Notes:

## Vehicle Information

Make:NISSAN

VIN:adnusun365u0159740

Odometer:127285 km

Vehicle Software Version:V10.24

## Inspection Result

The following systems are OK:

1.ENGINE

2.ABS

3.BCM

4.AIR BAG

5.EPS/DAST 3