

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:lukas@boschgezina.co.za

Sn:988579800333

Time:2024-07-18 09:45:38

Technician Name:Leseego

Order no:

Service fee:

Notes:

Vehicle Information

Year:2020

Make:HYUNDAI

Model:Grand i10/Xcent(BA)

VIN:MALA851ALLM059907

Displacement:G 1.0 MPI

Odometer:73155 km

Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.IC (Cluster Module)
- 6.MDPS (Motor Driven Power Steering)
- 7.IMMO (Immobilizer)