

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 14052

Make	RENAULT		
Model	KWID 1.0 DYNAMIQUE 5DR		
Vin	MEEBBA0070080668	4	
Engine Specifications	1.0	Petrol	
Vehicle Type	H/B		
Service Plan	N/A		

Year	2022
Km	44035
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	11/05/2027

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	•
Cluster	Within Specification	•	Electric Windows	Within Specification	-

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	-	Wiper Blades	Within Specification	-

BOSCH VEHICLE INSPECTION

Oil Service		33241 Km	Dip Stick	Within Specification
Oil Filter	Not Applicable	-	Oil Filler Cap	Within Specification
Fuel/Diesel Filter	Within Specification	~	Fan Belt	Not Applicable
Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	-	Alternator Belt	Not Applicable
Spark Plugs	Within Specification	-	Power Steering Belt	Not Applicable
Brake Fluid	Within Specification	-	Aircon Belt	Not Applicable
Antifreeze	Within Specification	-	Multi V belt	Within Specification
Rear Main Seal	Within Specification	-	Engine Mountings	Within Specification
Sump/Gasket	Within Specification	-	PCV Valve	Within Specification

BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	60%	-
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	-
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	~
Rear Drums	Within Specification	-
Rear Linings	60%	-
Brake Master	Within Specification	~
Hand Brake	Within Specification	-
Brake Calipers	Within Specification	-
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	-
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	-

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	-
Clutch Cable	Within Specification	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Within Specification	-
Cyl Leakage Test	Not Applicable	-
Road Test	Not Applicable	-
Handling	Not Applicable	~

Concluding Remarks

Bosch Technician

NEW Technician

MICHAEL JONES

-Select-

General Comments

Date of Inspection

13-Jun-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

