

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 13772

| Make                  | RENAULT                         |        |  |
|-----------------------|---------------------------------|--------|--|
| Model                 | KOLEOS 2.5 DYNAMIQUE/INTENS CVT |        |  |
| Vin                   | VF1RZG00262319031               | I      |  |
| Engine Specifications | 2.5                             | Petrol |  |
| Vehicle Type          | SUV                             |        |  |
| Service Plan          | N/A                             |        |  |

| Year          | 2019              |
|---------------|-------------------|
| Km            | 89475             |
| Transmission  | Automatic         |
| Colour        | BLUE              |
| Branch        | Bosch Car Service |
| Warranty Plan | N/A               |

| Interior              |                |   |                  |                |   |
|-----------------------|----------------|---|------------------|----------------|---|
| Radio / Entertainment | Good Condition | • | Aircon Controls  | Good Condition | • |
| Cluster               | Good Condition | - | Electric Windows | Good Condition | • |
|                       |                |   |                  |                |   |

| Exterior                |                |   |              |                |   |
|-------------------------|----------------|---|--------------|----------------|---|
| Windscreen              | Good Condition | - | Mag Wheels   | Good Condition | - |
| Side Mirrors / Electric | Good Condition | • | Wiper Blades | Good Condition | • |

## **BOSCH VEHICLE INSPECTION**

| Oil Service        |                | Km | Dip Stick           | Good Condition | • |
|--------------------|----------------|----|---------------------|----------------|---|
| Oil Filter         | Good Condition | •  | Oil Filler Cap      | Good Condition | • |
| Fuel/Diesel Filter | Good Condition | -  | Fan Belt            | Good Condition | - |
| Air Filter         | Good Condition | -  | Fan belt Tensioner  | Good Condition | • |
| Cabin Filter       | Good Condition | -  | Alternator Belt     | Good Condition | • |
| Spark Plugs        | Good Condition | -  | Power Steering Belt | Good Condition | • |
| Brake Fluid        | Good Condition | •  | Aircon Belt         | Good Condition | • |
| Antifreeze         | Good Condition | -  | Multi V belt        | Good Condition | • |
| Rear Main Seal     | Good Condition | •  | Engine Mountings    | Good Condition | - |
| Sump/Gasket        | Good Condition | •  | PCV Valve           | Good Condition | • |
|                    |                |    |                     |                |   |



| Braking System     |                |   |
|--------------------|----------------|---|
| Front Brake Pads   | 60%            | - |
| Front Brake Discs  | Good Condition | - |
| Front Brake Sensor | Not Applicable | - |
| Rear Brake Pads    | 60%            | • |
| Rear Brake Discs   | Good Condition | - |
| Rear Brake Sensor  | Not Applicable | • |
| Rear Drums         | Not Applicable | - |
| Rear Linings       | -Select-       | • |
| Brake Master       | Good Condition | - |
| Hand Brake         | Good Condition | - |
| Brake Calipers     | Good Condition | - |
| Brake Hose         | Good Condition | - |

| Cooling System    |                |   |
|-------------------|----------------|---|
| Radiator          | Good Condition | • |
| Radiator Hoses    | Good Condition | • |
| Waterpump         | Good Condition | • |
| Thermostat        | Good Condition | • |
| Aircon Gas        | Good Condition | • |
| Aircon Pump       | Good Condition | - |
| Aircon Condensor  | Good Condition | • |
| Interior Fan      | Good Condition | • |
| Interior Radiator | Good Condition | - |

| Fueling System  |                |   |
|-----------------|----------------|---|
| Intake Manifold | Good Condition | • |
| Throttle        | Good Condition | • |
| Turbo           | Good Condition | • |
| Injectors       | Good Condition | • |
| Fuel Pump       | Good Condition | • |
| Fuel Lines      | Good Condition | • |

| Ignition System |                |   |
|-----------------|----------------|---|
| Ignition Coils  | Good Condition | - |
| Glow Plugs      | Not Applicable | - |
| Distrubutor     | Not Applicable | - |
| HT Leads        | Not Applicable | - |



# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 13772

| Steering & Suspension |                |   |
|-----------------------|----------------|---|
| Steering Rack         | Good Condition | • |
| Power Steering Pump   | Good Condition | • |
| Wheel Alignment       | Good Condition | • |
| CV Joints             | Good Condition | • |
| CV Boots              | Good Condition | • |
| Shocks Front          | Good Condition | • |
| Shock Mountings Front | Good Condition | • |
| Shocks Rear           | Good Condition | • |
| Stabilizer Links      | Good Condition | • |
| Wheel Bearings        | Good Condition | • |
| Bearing Hubs          | Good Condition | • |
| Control Arms          | Good Condition | • |
| Sideshafts/Seal       | Good Condition | • |
| Propshaft             | Not Applicable | • |
| Wheel Nuts/Studs      | Good Condition | • |
| Tyres & Spare         | Good Condition | • |
| Mag Wheels/Hub Caps   | Good Condition | • |

| Transmission & Clutch |                |   |
|-----------------------|----------------|---|
| Clutch Kit            | Not Applicable | • |
| Clutch Master         | Not Applicable | • |
| Clutch Slave          | Not Applicable | • |
| Clutch Cable          | Not Applicable | - |
| Gearbox               | Not Applicable | - |
| Gear & Diff oil       | Not Applicable | • |
| Auto Transmission     | Good Condition | • |
| Gear Selector         | Good Condition | • |
| Gear Linkages         | Good Condition | - |

| Ignition System  |                |   |
|------------------|----------------|---|
| Diagnostics      | Not Applicable | - |
| Cyl Leakage Test | Not Applicable | - |
| Road Test        | Not Applicable | • |
| Handling         | Not Applicable | • |

#### **Concluding Remarks**

### Bosch Technician

-Select-

### General Comments

Date of Inspection



**NEW Technician** 



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

