

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: lukas@boschgezina.co.za

Sn: 988579800333

Time: 2024-05-30 15:16:04

Technician Name: shaun

Order no:

Service fee:

Notes:

Vehicle Information

Make: RENAULT

Model: KOLEOS II

VIN: VF1RZG00262319031

Displacement: G 1.6 T-GDI

Odometer: 89479 km

Vehicle Software Version: V10.38

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. ABS (Anti-lock Braking System)
3. IC (Instrument Cluster)
4. TCM (Transmission Control Module)
5. SRS (Supplemental Inflatable Restraint System)
6. AC (Air Conditioning)
7. UCH
8. Variable P.A.S
9. UPC
10. Multimedia Interface
11. Parking Prox Can
12. Radio