

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:11/01/2024 10:44:14

Technician Name:Christiaan

Vehicle Information

Year:2017

Make:NISSAN

Model:NV200 (EURO product)

VIN:VSKYBAM20Z0160685

Displacement:D 1.4 TCI-U2

Odometer:126128 km

Vehicle Software Version:V10.48

Inspection Result

The following systems are OK:

- 1.Engine Control Module(ECM)
- 2.Anti-lock Brake System(ABS)
- 3.Instrument cluster(IC)
- 4.Body Control System(BCM)
- 5.Supplemental Restraint System(SRS)
- 6.Electric Power Steering(EPS)
- 7.Intelligent Power Distribution Unit(IPDU)

