

Diagnostic Report

THINKCAR

Time: 11/11/2024 11:02:39

Customer Name: N/A

Technician Name: mike

Shop Name: Bosch Gezina	Telephone: N/A
Email: karika@bosch	Country: South Africa
State: Gauteng	City: Pretoria
Address1: N/A	Address2: N/A

Make: CHRYSLER	Model: Renegade(BU)
Year: 2015	Displacement: G 1.2 MPI KAPPA PE
VIN: 1C4BU0000FPB61512	Odometer: 114987 km
License #: N/A	Vehicle Software Version: V10.48

Pre-Scan

11/11/2024 11:02:39

System(5)	Status
PCM (Powertrain Control Module)	No Fault
BCM (Body Control Module - TIPMCGW/FCMCGW)	No Fault
IPC (Instrument Panel Cluster)	No Fault
RFH/TPMS (Radio Frequency Hub - Tire)	No Fault
ACC (Adaptive Cruise Control)	No Fault