

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:mariska@boschgezina.co.za  
Sn:988579800333  
Time:2024-08-20 15:22:18  
Technician Name:Mike Jones  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year:2018  
Make:USAFORD  
Model:Ranger / Mazda B-Ser  
VIN:AFANXXMJ2NJS61528  
Displacement:G 1.2 MPI  
Odometer:161826 km  
Vehicle Software Version:V10.76

## Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.BCMII (Body Control Module)
- 4.FCIM (Front Controls Interface Module)
- 5.GWM (Gateway Module A)
- 6.IPC (Instrument Panel Control Module)
- 7.PCM (Powertrain Control Module)
- 8.PSCM (Power Steering Control Module)
- 9.RCM (Restraint Control Module)
- 10.RTM (Radio Transceiver Module)
- 11.SCCM (Steering Column Control Module)
- 12.TRM (Trailer Module)