

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-09-03 07:14:14

Technician Name:Dries

Order no:

Service fee:

Notes:

Vehicle Information

Year:2020

Make:KIA

Model:Picanto/Morning(JA)

VIN:KNAB3512LLT615524

Displacement:G 1.2 MPI KAPPA

Odometer:56734 km

Vehicle Software Version:V10.38

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS/ESC
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.AC (Air Conditioning)
- 6.IC (Instrument Cluster)
- 7.BCM (Body Control Module)
- 8.TPMS (Tire Pressure Monitoring System)
- 9.MDPS (Motor Driven Power Steering)
- 10.IMMO (Immobilizer)
- 11.CODE (Transmitter Code Saving)