Make	ТОУОТА	
Model	ETIOS 1.5 Xi 5Dr	
Vin	MBJM29BT70206170	6
Engine Specifications	1.5	Petrol
Vehicle Type	H/B	

Year	2019
Km	93587
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Good Condition	_
Cluster	Within Specification	-	Electric Windows	Not Applicable	-

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Not Applicable	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	lacksquare
Oil Filter	Within Specification		Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	lacksquare
Cabin Filter	Within Specification		Alternator Belt	No Cracks	<b>V</b>
Spark Plugs	Within Specification		Power Steering Belt	Not Applicable	_
Brake Fluid	Good Condition		Aircon Belt	No Cracks	_
Antifreeze	Not Applicable		Multi V belt	No Cracks	_
Rear Main Seal	No Visible Leaks		Engine Mountings	Good Condition	
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	<b>\rightarrow</b>

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	Good Condition	•
Hand Brake	Within Specification	•
Brake Calipers	Good Condition	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	No Visible Leaks	lacksquare
Waterpump	Within Specification	-
Thermostat	Within Specification	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	lacksquare

Fueling System		
Intake Manifold	Within Specification	-
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	lacksquare
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	-

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	<b>—</b>



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	lacksquare
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	lacksquare
Stabilizer Links	Good Condition	lacksquare
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	lacksquare
Control Arms	Good Condition	<b>—</b>
Sideshafts/Seal	No Visible Leaks	<b>—</b>
Propshaft	Not Applicable	<b>—</b>
Wheel Nuts/Studs	Good Condition	<b>\</b>
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	lacksquare

Transmission & Clutch		
Clutch Kit	Within Specification	
Clutch Master	Within Specification	-
Clutch Slave	Not Applicable	
Clutch Cable	Within Specification	•
Gearbox	Good Condition	-
Gear & Diff oil	Within Specification	
Auto Transmission	Not Applicable	
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	-
Handling	Good Condition	<b>~</b>

Concluding Remarks		

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
RIAAN MEINTJIES	24-Oct-2024



