

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 14717

Make	GWM	
Model	H6 1.5T CITY	
Vin	LGWEF4A57EF63216	39
Engine Specifications	1.5	Petrol
Vehicle Type	H/B	
Service Plan	N/A	

Year	2015
Km	131416
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Good Condition	•
Cluster	Within Specification	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Good Condition	-

BOSCH VEHICLE INSPECTION

Oil ServiceKmDip StickWithin SpecificationImage: Constraint of the sectificationOil FilterWithin SpecificationImage: Constraint of the sectificationOil Filter CapNo Visible LeaksImage: Constraint of the sectificationAir FilterWithin SpecificationImage: Constraint of the sectificationImage: Constraint of the sectificationFan BeltNo CracksImage: Constraint of the sectificationCabin FilterWithin SpecificationImage: Constraint of the sectificationImage: Constraint of the sectificationImag						
Fuel/Diesel FilterWithin SpecificationImage: ConstructionFan BeltNo CracksImage: ConstructionAir FilterWithin SpecificationImage: ConstructionImage:	Oil Service		Km	Dip Stick	Within Specification	•
Air FilterWithin SpecificationImage: ConstructionFan belt TensionerWithin SpecificationImage: ConstructionCabin FilterWithin SpecificationImage: ConstructionAlternator BeltNo CracksImage: ConstructionSpark PlugsWithin SpecificationImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionBrake FluidGood ConditionImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionAntifreezeNot ApplicableImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionImage: ConstructionRear Main SealNo Visible LeaksImage: ConstructionImage: ConstructionImage: ConstructionImage: Construction	Oil Filter	Within Specification	-	Oil Filler Cap	No Visible Leaks	•
Cabin FilterWithin SpecificationImage: Cabin FilterAlternator BeltNo CracksSpark PlugsWithin SpecificationImage: Cabin FilterNo CracksImage: Cabin FilterBrake FluidGood ConditionImage: Cabin FilterNo CracksImage: Cabin FilterAntifreezeNot ApplicableImage: Cabin FilterNo CracksImage: Cabin FilterRear Main SealNo Visible LeaksImage: Cabin FilterImage: Cabin FilterImage: Cabin Filter	Fuel/Diesel Filter	Within Specification	-	Fan Belt	No Cracks	•
Spark Plugs Within Specification Image: Power Steering Belt No Cracks Image: Power Steering Belt Brake Fluid Good Condition Image: Power Steering Belt No Cracks Image: Power Steering Belt Antifreeze Not Applicable Image: Power Steering Belt No Cracks Image: Power Steering Belt Rear Main Seal No Visible Leaks Image: Power Steering Belt No Cracks Image: Power Steering Belt	Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	-
Brake Fluid Good Condition Image: Condition Aircon Belt No Cracks Antifreeze Not Applicable Image: Condition Image: Condition Image: Condition Rear Main Seal No Visible Leaks Image: Condition Image: Condition Image: Condition	Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	•
Antifreeze Not Applicable Multi V belt No Cracks Rear Main Seal No Visible Leaks Image: Construction of the second s	Spark Plugs	Within Specification	-	Power Steering Belt	No Cracks	•
Rear Main Seal No Visible Leaks Engine Mountings Within Specification	Brake Fluid	Good Condition	-	Aircon Belt	No Cracks	•
	Antifreeze	Not Applicable	-	Multi V belt	No Cracks	•
Sump/Gasket No Visible Leaks PCV Valve Within Specification	Rear Main Seal	No Visible Leaks	-	Engine Mountings	Within Specification	•
	Sump/Gasket	No Visible Leaks	-	PCV Valve	Within Specification	•

BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	80%	-
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Good Condition	•
Hand Brake	Within Specification	•
Brake Calipers	Good Condition	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Good Condition	•
Aircon Pump	Within Specification	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Within Specification	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Good Condition	-
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	-
Shocks Rear	Good Condition	-
Stabilizer Links	Good Condition	-
Wheel Bearings	Within Specification	-
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	-
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	-
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	-

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	-

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	•
Road Test	Good Condition	•
Handling	Good Condition	•

Concluding Remarks

Bosch Technician

NEW Technician

RIAAN MEINTJIES

-Select-

General Comments

Date of Inspection

22-Jul-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

