

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:mariska@boschgezina.co.za  
Sn:988579800333  
Time:2024-08-01 15:52:43  
Technician Name:Raymond  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year:2019  
Make:USAFORD  
Model:Ranger / Mazda B-Ser  
VIN:AFAPXXMJ2PKU64371  
Displacement:G 1.0 MPI KAPPA  
Odometer:89497 km  
Vehicle Software Version:V10.76

## Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.BCMII (Body Control Module)
- 5.FCDIM (Front Control/Display Interface Module)
- 6.FCIM (Front Controls Interface Module)
- 7.GWM (Gateway Module A)
- 8.IPC (Instrument Panel Control Module)
- 9.PAM (Parking Aid Module)
- 10.PCM (Powertrain Control Module)
- 11.PSCM (Power Steering Control Module)
- 12.RCM (Restraint Control Module)
- 13.RTM (Radio Transceiver Module)
- 14.SCCM (Steering Column Control Module)
- 15.TRM (Trailer Module)