

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:johan@boschgezina.co.za

Sn:988579800333

Time:2024-07-23 12:20:17

Technician Name:shaun

Order no:

Service fee:

Notes:

Vehicle Information

Year:2019

Make:KIA

Model:Picanto/Morning(JA)

VIN:KNAB2511LKT364403

Displacement:G 1.0 MPI KAPPA

Odometer:76214 km

Vehicle Software Version:V10.38

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.Airbag(Event #1)
- 3.Airbag(Event #2)
- 4.AC (Air Conditioning)
- 5.IC (Instrument Cluster)
- 6.MDPS (Motor Driven Power Steering)
- 7.IMMO (Immobilizer)