

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-09-10 10:35:46

Technician Name:Wimpie F

Order no:

Service fee:

Notes:

Vehicle Information

Year:2018

Make:MAZDA

Model:MAZDA2 / DEMIO

VIN:MM6DJ2HA6JW364592

Odometer:116280 km

Vehicle Software Version:V10.34

Inspection Result

The following systems are OK:

- 1.BCM#1 (Body Control Module)
- 2.IC (Instrument Cluster)
- 3.PCM (Powertrain Control Module)
- 4.RCM (Restraint Control Module)
- 5.ABS (Anti-Lock Brake System)
- 6.CMU (Connectivity Master Unit)
- 7.EPS (Electronic Power Steering)
- 8.ESU (Electric Supply Unit)
- 9.SSU#1 (Start Stop Unit)