Make	TOYOTA		
Model	HILUX 2.0 VVTi S P/U S/C		
Vin	AHTCW8CE	3101964675	
Engine Specifications	2.0	Petrol	-
Vehicle Type	S/C		
Service Plan	N/A		

Year	2022
Km	8010
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Not Applicable	•
Cluster	Good Condition	•	Electric Windows	Good Condition	<b>V</b>

Exterior					
Windscreen	Good Condition	<b>~</b>	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition	•
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	•	Alternator Belt	Good Condition	•
Spark Plugs	Good Condition	•	Power Steering Belt	Good Condition	<b>~</b>
Brake Fluid	Good Condition	•	Aircon Belt	Good Condition	<b>~</b>
Antifreeze	Good Condition	•	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	•	Engine Mountings	Good Condition	•
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	V

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Good Condition	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Good Condition	•
Rear Linings	60%	<b>—</b>
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	<b>—</b>
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	-
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Not Applicable	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	<b>\</b>

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Not Applicable	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>~</b>
HT Leads	Good Condition	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	lacksquare
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	Good Condition	•
Propshaft	Good Condition	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Good Condition	
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	<b>T</b>

Ignition System		
Diagnostics	Good Condition	
Cyl Leakage Test	Good Condition	_
Road Test	Good Condition	-
Handling	Good Condition	<b>~</b>

Bosch Technician	General Comments
Basal Johnson	
NEW Technician	Date of Inspection
NEW rechnician	30-Jul-2024



Concluding Remarks

