. . . . . . . . . . . . . . . . . . .

## All System Diagnostic Report

The Report is created by **THINKCAR** 

Repair Shop
-------------

Shop Name:bosch service centre Address:564 Steve Biko Road Telephone:0123355737 Email:lukas@boschgezina.co.za Sn:988579800333 Time:2024-07-30 13:57:26 Technician Name:Basal Customer Name:citton cars Order no: Service fee: Notes:

. . . . . . . . . . . . . . . . . . .

## **Vehicle Information**

Year:2015 Make:TOYOTA Model:Hilux VIN:AHTCW8CB101964675 Displacement:D 1.4 TCI-U2 Odometer:8014.00 km Vehicle Software Version:V10.44

## **Inspection Result**

The following systems are OK: 1.EOBD/OBD II 2.ECMECT (Engine and ECT) 3.CCS (Cruise Control) 4.ABS (Anti-lock Braking System)/VSC (Vehicle Stability Control)/TRC (Traction Control System) 5.SRS (Supplemental Inflatable Restraint System) 6.CM (Combination Meter) 7.IMMO (Immobiliser)