Make	FORD	
Model	FOCUS 1.0 ECOBOOST AMBIENTE 5Dr	
Vin	WF05XXGCC5HM648	361
Engine Specifications	1.0	Petrol
Vehicle Type	H/B	
Service Plan	N/A	

Year	2017
Km	124625
Transmission	Manual
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	—	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition	•
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	•	Alternator Belt	Good Condition	•
Spark Plugs	Good Condition	•	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	•	Aircon Belt	Good Condition	~
Antifreeze	Good Condition	•	Multi V belt	Good Condition	~
Rear Main Seal	Good Condition	•	Engine Mountings	Good Condition	~
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	~

Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Good Condition	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Good Condition	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	~
Thermostat	Good Condition	•
Aircon Gas	Good Condition	
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	lacksquare
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	V
Turbo	Good Condition	•
Injectors	Good Condition	lacksquare
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	T
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	Good Condition	T
Propshaft	Not Applicable	T
Wheel Nuts/Studs	Good Condition	T
Tyres & Spare	Good Condition	—
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Good Condition	
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	T

Ignition System		
Diagnostics	Good Condition	
Cyl Leakage Test	Good Condition	-
Road Test	Good Condition	-
Handling	Good Condition	-

Bosch Technician	General Comments
-Select-	
NEW Technician	Date of Inspection



Concluding Remarks

