

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-09-13 14:21:53

Technician Name:Raymond

Order no:

Service fee:

Notes:

Vehicle Information

Make:NISSAN

VIN:ADNUSN1D5U0165138

Displacement:G 1.4 DOHC

Odometer:127477 km

Vehicle Software Version:V10.46

Inspection Result

The following systems are OK:

- 1.Anti-lock Brake System(ABS)
- 2.Body Control System(BCM)
- 3.Supplemental Restraint System(SRS)