

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:juan-dre@boschgezina.co.za
Sn:988579800333
Time:2024-08-26 11:17:40
Technician Name:shaun
Order no:
Service fee:
Notes:

Vehicle Information

Year:2019
Make:KIA
Model:Sportage(QLE)
VIN:U5YPG81AMKL653332
Displacement:G 2.0 MPI NU
Odometer:87255 km
Vehicle Software Version:V10.38

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ESP (Electronic Stability Program)
- 4.Airbag(Event #1)
- 5.Airbag(Event #2)
- 6.IC (Instrument Cluster)
- 7.SJB (Smart Junction Block)
- 8.Motor Driven Power Steering(C-Type)
- 9.Motor Driven Power Steering(R-Type RHD)
- 10.IMMO (Immobilizer)