

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:johan@boschgezina.co.za

Sn:988579800333

Time:2024-08-13 14:59:54

Technician Name:Basal

Customer Name:citton cars

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2019

Make:KIA

Model:Sportage(QLE)

VIN:U5YPG814MKL654749

Displacement:G 1.6 GDI GAMMA

Odometer:60094 km

Vehicle Software Version:V10.38

## Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ESP (Electronic Stability Program)
- 4.Airbag(Event #1)
- 5.Airbag(Event #2)
- 6.IC (Instrument Cluster)
- 7.SJB (Smart Junction Block)
- 8.Motor Driven Power Steering(C-Type)
- 9.Motor Driven Power Steering(R-Type RHD)
- 10.IMMO (Immobilizer)