Make	NISSAN	
Model	NP200 1.6 A/C SAFETY PACK P/U S/C	
Vin	ADNUSN1D5U0166437	
Engine Specifications	1.6 Petrol	▼
Vehicle Type	S/C	
Service Plan	N/A	

Year	2019
Km	132372
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Not Applicable	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Renewed	~	Mag Wheels	Not Applicable	—
Side Mirrors / Electric	Not Applicable	•	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		132372 Km	Dip Stick	No Visible Leaks	•
Oil Filter	Renewed	•	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Not Applicable	•	Fan Belt	No Cracks	•
Air Filter	Within Specification	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Within Specification	-	Alternator Belt	Not Applicable	•
Spark Plugs	Within Specification	•	Power Steering Belt	Not Applicable	•
Brake Fluid	Good Condition	-	Aircon Belt	Not Applicable	•
Antifreeze	Good Condition	•	Multi V belt	Not Applicable	•
Rear Main Seal	No Visible Leaks	~	Engine Mountings	Good Condition	-
Sump/Gasket	Renewed	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	~
Thermostat	Good Condition	
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	~

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Not Applicable	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Good Condition	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	—
Power Steering Pump	Good Condition	•
Wheel Alignment	Renewed	
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	lacksquare
Stabilizer Links	Renewed	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	lacksquare
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	-
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Renewed	
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	-
Clutch Master	Good Condition	~
Clutch Slave	Good Condition	~
Clutch Cable	Good Condition	~
Gearbox	Good Condition	~
Gear & Diff oil	Not Applicable	~
Auto Transmission	Not Applicable	~
Gear Selector	Good Condition	~
Gear Linkages	Good Condition	V

Ignition System		
Diagnostics	No Fault Code	
Cyl Leakage Test	Good Condition	_
Road Test	Good Condition	-
Handling	Good Condition	~

Bosch Technician	General Comments
-Select-	
NEW Technician	Date of Inspection
HENDRIE	



Concluding Remarks

