Make	CHERY	
Model	TIGGO 4 PRO 1.5 COMFORT CVT	
Vin	LVVDB21B2ND36657	"2
Engine Specifications	1.5	Petrol
Vehicle Type	SUV	
Service Plan	23/01/2028	

Year	2023
Km	29195
Transmission	Automatic
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	23/01/2028

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	<b>—</b>	Wiper Blades	Good Condition	<b>—</b>

BOSCH VEHICLE INSPECTION				
Engine				
Oil Service		Km	Dip Stick	Good Condition
Oil Filter	Good Condition	<b>~</b>	Oil Filler Cap	Good Condition
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition
Cabin Filter	Good Condition	<b>~</b>	Alternator Belt	Good Condition
Spark Plugs	Good Condition	•	Power Steering Belt	Good Condition
Brake Fluid	Good Condition	•	Aircon Belt	Good Condition
Antifreeze	No Visible Leaks	•	Multi V belt	Good Condition
Rear Main Seal	No Visible Leaks	<b>~</b>	Engine Mountings	Good Condition
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Good Condition	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	80%	•
Rear Brake Discs	Good Condition	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Good Condition	<b>—</b>
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	<b>~</b>
Radiator Hoses	Good Condition	<b>V</b>
Waterpump	Good Condition	<b>V</b>
Thermostat	Good Condition	<b>~</b>
Aircon Gas	Good Condition	<b>\rightarrow</b>
Aircon Pump	Good Condition	<b>~</b>
Aircon Condensor	Good Condition	₩
Interior Fan	Good Condition	▼
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	lacksquare
Turbo	Good Condition	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	-Select-	•
Distrubutor	-Select-	•
HT Leads	-Select-	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	<b>—</b>
Power Steering Pump	Good Condition	<b>—</b>
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	<b>—</b>
CV Boots	Good Condition	•
Shocks Front	Good Condition	<b>V</b>
Shock Mountings Front	Good Condition	<b>V</b>
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	<b>—</b>
Control Arms	Good Condition	<b>—</b>
Sideshafts/Seal	Good Condition	<b>~</b>
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	<b>—</b>
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	<b>~</b>

Transmission & Clutch		
Clutch Kit	-Select-	
Clutch Master	-Select-	
Clutch Slave	-Select-	
Clutch Cable	-Select-	
Gearbox	-Select-	lacksquare
Gear & Diff oil	-Select-	
Auto Transmission	Good Condition	
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	-Select-	<b>V</b>
Cyl Leakage Test	-Select-	<b>~</b>
Road Test	-Select-	<b>~</b>
Handling	-Select-	•

Concluding Remarks		

Bosch Technician	
-Select-	Ţ.

General Comments		

NEW Technician	
SHAUN OLIVIER	

Date of Inspection



