Make	GWM	
Model	STEED 5 2.2 MPi WORKHORSE P/U S/C	
Vin	LGWCA2379NB66735	58
Engine Specifications	2.2	Diesel
Vehicle Type	S/C	
Service Plan	N/A	

Year	2023
Km	68526
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	<b>~</b>	Aircon Controls	Within Specification	_
Cluster	Within Specification	<b>—</b>	Electric Windows	Within Specification	_

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		68527 Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification	<b>—</b>	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	<b>—</b>	Fan Belt	Within Specification	•
Air Filter	Within Specification	<b>—</b>	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	<b>—</b>	Alternator Belt	Within Specification	•
Spark Plugs	Within Specification	<b>—</b>	Power Steering Belt	Within Specification	•
Brake Fluid	Within Specification	<b>—</b>	Aircon Belt	Within Specification	•
Antifreeze	Within Specification	lacksquare	Multi V belt	Within Specification	•
Rear Main Seal	Within Specification	<b>—</b>	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	Within Specification	lacksquare
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	_
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	_
Thermostat	Within Specification	_
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	_
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	lacksquare
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	lacksquare

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	<b>V</b>
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	Within Specification	
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	lacksquare
Shocks Rear	Within Specification	lacksquare
Stabilizer Links	Within Specification	lacksquare
Wheel Bearings	Within Specification	lacksquare
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	lacksquare
Sideshafts/Seal	Within Specification	lacksquare
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	
Tyres & Spare	Within Specification	
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	
Clutch Master	Within Specification	
Clutch Slave	Not Applicable	
Clutch Cable	Within Specification	
Gearbox	Within Specification	
Gear & Diff oil	Within Specification	
Auto Transmission	Not Applicable	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Within Specification	<b>\</b>
Cyl Leakage Test	Within Specification	<b>~</b>
Road Test	Within Specification	-
Handling	Within Specification	<b>~</b>

Bosch Technician	General Comments
Ricardo Myburgh	
NEW Technician	Date of Inspection
	24-Jun-2024



**Concluding Remarks** 

