



Vehicle Information

Brand: FORD	VIN: MAJAXXMRKAKE66806	Plate Number:
Model: EcoSport	Mileage:	Color:
Year: 2019	Capacity: 1.5L	Status: Unset status
Engine: Duratorq-Turbo Diesel Common Rail Injection	Reference:	Date: 07.01.2025 14:13:05

Automatic scanning results

System Name	Status/Count
01-PCM--Powertrain Control Module	Pass No Fault
02-ABS--Antilock braking system	Pass No Fault
03-BdyCM--Body Control Module	Pass No Fault
04-IPC--Instrument Panel Control Module	Pass No Fault
05-RCM--Restraint Control Module	Pass No Fault
06-GWM--Gateway Module A	Pass No Fault
07-HVAC--Heating Ventilation Air Conditioning	Pass No Fault
08-PAM--Parking Aid Module	Pass No Fault
09-APIM--Accessory Protocol Interface Module	Pass No Fault
10-PSCM--Power Steering Control Module	Pass No Fault
11-ACM--Audio Control Module	Pass No Fault
12-SCCM--Steering Column Control Module	Pass No Fault



Contact Information

Name:

Address: Pretoria Gauteng

Phone:

Email:

Website:

APP Version: 1.4.8