

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 14158

Make	GWM	
Model	STEED 5 2.2 MPi WORKHORSE P/U S/C	
Vin	LGWCA2375NB66728	39
Engine Specifications	2.2	Petrol
Vehicle Type	S/C	
Service Plan	N/A	

Year	2023
Km	61468
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Working Condition	-	Aircon Controls	Working Condition	•
Cluster	Good Condition	-	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	-Select-	•

## **BOSCH VEHICLE INSPECTION**

Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	-	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Not Applicable	•
Air Filter	Good Condition	-	Fan belt Tensioner	Within Specification	-
Cabin Filter	Within Specification	-	Alternator Belt	Within Specification	•
Spark Plugs	Within Specification	-	Power Steering Belt	Not Applicable	•
Brake Fluid	Not Applicable	-	Aircon Belt	Not Applicable	-
Antifreeze	Not Applicable	•	Multi V belt	Within Specification	•
Rear Main Seal	Good Condition	-	Engine Mountings	Within Specification	-
Sump/Gasket	Good Condition	-	PCV Valve	Within Specification	•



Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	80%	•
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	Within Specification	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Within Specification	•
Waterpump	Good Condition	•
Thermostat	Not Applicable	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	-
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Not Applicable	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Within Specification	•



# **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Within Specification	•
CV Joints	Not Applicable	•
CV Boots	Not Applicable	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	-
Control Arms	Good Condition	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Good Condition	•
Cyl Leakage Test	Not Applicable	•
Road Test	Within Specification	•
Handling	Good Condition	

#### **Concluding Remarks**

### Bosch Technician

Adriaan Rademeyer

General Comments

NEW Technician

BOTE

### Date of Inspection



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

