

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 17578

Make	FORD		
Model	FIGO 1.5Ti VCT TREND (5DR)		
Vin	MAJGXXMTKGJT67388		
Engine Specifications	1.5 Petrol		
Vehicle Type	H/B		
Service Plan	N/A		

Year	2019
Km	112462
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Within Specification	-	Wiper Blades	Renewed	-

## **BOSCH VEHICLE INSPECTION**

Oil Service		104604 Km	Dip Stick	Within Specification
Oil Filter	No Visible Leaks	•	Oil Filler Cap	Within Specification
Fuel/Diesel Filter	Not Applicable	•	Fan Belt	Not Applicable
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	•	Alternator Belt	No Cracks
Spark Plugs	No Fault Code	•	Power Steering Belt	Not Applicable
Brake Fluid	Within Specification	•	Aircon Belt	No Cracks
Antifreeze	Within Specification	•	Multi V belt	No Cracks
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification

# BOSCH INSPECTION REPORT

60%	-
Within Specification	•
Not Applicable	•
-Select-	•
Not Applicable	•
Not Applicable	-
Within Specification	-
80%	•
No Visible Leaks	•
Within Specification	-
No Visible Leaks	•
No Visible Leaks	-
	Within Specification Not Applicable -Select- Not Applicable Not Applicable Within Specification 80% No Visible Leaks Within Specification No Visible Leaks

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	<b>•</b>
Aircon Pump	No Fault Code	-
Aircon Condensor	No Visible Leaks	-
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	No Fault Code	•
Turbo	Not Applicable	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	-
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	-

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	No Visible Leaks	•
Clutch Slave	No Visible Leaks	•
Clutch Cable	Not Applicable	•
Gearbox	No Visible Leaks	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	•
Handling	Within Specification	•

#### **Concluding Remarks**

#### Bosch Technician

Dries Olwagen

**NEW Technician** 

### General Comments

Date of Inspection



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

