

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:  
Address:  
Telephone:N/A  
Sn:988579800333  
Time:12/13/2024 15:29:56  
Technician Name:hennie

## Vehicle Information

Year:2018  
Make:MAZDA  
Model:MAZDA2 / DEMIO  
VIN:MM6DJ2HAAJW367541  
Displacement:G 1.0 MPI  
Odometer:95874 km  
Vehicle Software Version:V10.38

## Inspection Result

The following systems are OK:

- 1.BCM#1 (Body Control Module)
- 2.IC (Instrument Cluster)
- 3.PCM (Powertrain Control Module)
- 4.RCM (Restraint Control Module)
- 5.TCM (Transmission Control Module)
- 6.ABS (Anti-Lock Brake System)
- 7.EATC#1 (Electronic Air Temperature Controller)
- 8.CMU (Connectivity Master Unit)
- 9.EPS (Electronic Power Steering)
- 10.ESU (Electric Supply Unit)
- 11.FSC (Forward Sensing Camera)
- 12.HUD (Head Up Display)
- 13.PSM#1 (Parking Sensor Module)
- 14.SSU#1 (Start Stop Unit)