

# All System Diagnostic Report

The Report is created by **THINKCAR**

---

## Repair Shop

Shop Name:  
Address:  
Telephone:N/A  
Sn:988579800333  
Time:01/07/2025 15:54:06  
Technician Name:wimpie

---

## Vehicle Information

Year:2015  
Make:TOYOTA  
Model:Hilux  
VIN:AHTGA3DD100968069  
Displacement:G 1.0 MPI KAPPA  
Odometer:176422.00 km  
Vehicle Software Version:V10.48

---

## Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.ECMECT (Engine and ECT)
- 3.CCS (Cruise Control)
- 4.ABS (Anti-lock Braking System)/VSC (Vehicle Stability Control)/TRC (Traction Control System)
- 5.SRS (Supplemental Inflatable Restraint System)
- 6.AC (Air Conditioning)
- 7.FWD (Four Wheel Drive)
- 8.CM (Combination Meter)
- 9.NS (Navigation System)
- 10.IMMO (Immobiliser)