

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: mariska@boschgezina.co.za  
Sn: 988579800333  
Time: 2024-08-13 14:52:08  
Technician Name: Raymond  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year: 2015  
Make: AUDI  
VIN: WAUZZZ8K4FA068115  
Displacement: D 2.0 TCI-R  
Odometer: 134830 km  
Vehicle Software Version: V10.26

## Inspection Result

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.05 Access/Start Authorization
- 5.08 Climate Control Module
- 6.09 Electronic Central Electric
- 7.15 Airbag
- 8.16 Steering Column Electronics Systems
- 9.17 Instrument Cluster
- 10.19 Data Bus OBD Interface
- 11.2E Media Player 3
- 12.42 Driver's Door Electronics
- 13.44 Power Steering
- 14.46 Comfort System Central Control Module
- 15.47 Sound System
- 16.52 Passenger's Door Electronics
- 17.53 Parking Brake
- 18.56 Radio
- 19.62 Left Rear Door Electronics
- 20.72 Right Rear Door Electronics
- 21.77 Telephone