

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: Bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: jaco@boschgezina.co.za

Sn: 988579800333

Time: 2024-03-13 16:00:58

Technician Name: Raymond

Customer Name: citton cars

Vehicle Information

Make: NISSAN

VIN: SJNFAAJ11ZZ068480

Odometer: 128326 km

Vehicle Software Version: V10.32

Inspection Result

The following systems are OK:

1. ENGINE

2. ABS

3. METER/M&A

4. BCM

5. AIR BAG

6. HVAC

7. MULTI AV

8. EHS/PKB

9. EPS/DAST 3

10. IPDM E/R

11. AIR PRESSURE MONITOR

12. CAN GATEWAY

13. AVM

14. CHASSIS CONTROL