Make	JEEP		
Model	GRAND CHEROKEE 3.6 OVERLAND		
Vin	1C4RJFGG4FC86852	22	
Engine Specifications	3.6	Petrol	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2015
Km	103789
Transmission	Automatic
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	<b>~</b>

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Good Condition		Oil Filler Cap	Within Specification	<b>~</b>
Fuel/Diesel Filter	Not Applicable		Fan Belt	No Cracks	<b>—</b>
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	No Fault Code		Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks		Aircon Belt	No Cracks	•
Antifreeze	No Visible Leaks		Multi V belt	No Cracks	<b>~</b>
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	<b>\rightarrow</b>
Radiator Hoses	No Visible Leaks	<b>—</b>
Waterpump	No Visible Leaks	<b>~</b>
Thermostat	No Visible Leaks	_
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	<b>V</b>
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	No Fault Code	lacksquare
Turbo	Not Applicable	lacksquare
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	lacksquare

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	<b>—</b>



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	No Visible Leaks	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	
Shocks Rear	No Visible Leaks	
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	
Mag Wheels/Hub Caps	Within Specification	•

**BOSCH CAR SERVICE** 

**PRETORIA** 

Transmission & Clutch		
Clutch Kit	Not Applicable	
Clutch Master	Not Applicable	
Clutch Slave	Not Applicable	
Clutch Cable	Not Applicable	•
Gearbox	No Visible Leaks	
Gear & Diff oil	No Visible Leaks	
Auto Transmission	No Visible Leaks	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Bosch Technician		General Comments
Dries Olwagen	•	
NEW Technician		Date of Inspection



**Concluding Remarks** 

