Make	FORD		
Model	ECOSPORT 1.0 ECOBOOST TITANIUM		
Vin	MAJAXXMRKAEG68	580	
Engine Specifications	1.0	Petrol	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2015
Km	77342
Transmission	Manual
Colour	GOLD
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	<b>~</b>	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	<b>—</b>	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition	•
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	•	Alternator Belt	Good Condition	•
Spark Plugs	Good Condition	•	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	•	Aircon Belt	Good Condition	<b>~</b>
Antifreeze	Good Condition	•	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	•	Engine Mountings	Good Condition	•
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	V

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Good Condition	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Good Condition	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	<b>—</b>
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	<b>~</b>
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Good Condition	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	<b>V</b>
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>V</b>
HT Leads	Not Applicable	<b>V</b>



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	<b>V</b>
Wheel Alignment	Good Condition	<b>\</b>
CV Joints	Good Condition	<b>V</b>
CV Boots	Good Condition	lacksquare
Shocks Front	Good Condition	<b>V</b>
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	lacksquare
Stabilizer Links	Good Condition	<b>V</b>
Wheel Bearings	Good Condition	<b>V</b>
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	<b>V</b>
Sideshafts/Seal	Good Condition	<b>V</b>
Propshaft	Not Applicable	<b>V</b>
Wheel Nuts/Studs	Good Condition	<b>V</b>
Tyres & Spare	Good Condition	<b>V</b>
Mag Wheels/Hub Caps	Good Condition	<b>V</b>

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	<b>T</b>
Clutch Slave	Good Condition	<b>V</b>
Clutch Cable	Not Applicable	<b>V</b>
Gearbox	Good Condition	<b>V</b>
Gear & Diff oil	Good Condition	<b>V</b>
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	<b>V</b>
Gear Linkages	Good Condition	<b>V</b>

Ignition System		
Diagnostics	Good Condition	<b>—</b>
Cyl Leakage Test	Good Condition	<b>\rightarrow</b>
Road Test	Good Condition	<b>~</b>
Handling	Good Condition	•

Concluding Nemarks	
Bosch Technician	General Comments
-Select-	
NEW Technician	Date of Inspection



