

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:johan@boschgezina.co.za

Sn:988579800333

Time:2024-08-15 10:33:07

Technician Name:Eugene

Order no:

Service fee:

Notes:

Vehicle Information

Make:RENAULT

Model:CLIO IV

VIN:VF15R4M0E51369393

Displacement:G 1.6 GDI GAMMA

Odometer:119007 km

Vehicle Software Version:V10.36

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.IC (Instrument Cluster)
- 4.TCM (Transmission Control Module)
- 5.SRS (Supplemental Inflatable Restraint System)
- 6.UCH
- 7.AC (Air Conditioning)
- 8.Variable P.A.S
- 9.UPC
- 10.Parking Prox Can
- 11.Radio
- 12.Hands-Free Module