Make	VOLKSWAGEN		
Model	MOVE UP! 1.0 5DR		
Vin	WVWZZZAAZKD16988	30	
Engine Specifications	1.0	Petrol	
Vehicle Type	H/B		
Service Plan	N/A		

Year	2019
Km	118317
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	—	Aircon Controls	Good Condition	•
Cluster	Within Specification	—	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Not Applicable	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Renewed		Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	Within Specification		Power Steering Belt	Not Applicable	•
Brake Fluid	Good Condition		Aircon Belt	No Cracks	-
Antifreeze	Good Condition		Multi V belt	No Cracks	T
Rear Main Seal	No Visible Leaks		Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	80%	—
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	—
Rear Brake Pads	-Select-	—
Rear Brake Discs	Not Applicable	—
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	—
Brake Master	Good Condition	•
Hand Brake	Within Specification	—
Brake Calipers	Within Specification	—
Brake Hose	No Visible Leaks	—

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Good Condition	-
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	
Wheel Alignment	Within Specification	
CV Joints	Good Condition	
CV Boots	No Visible Leaks	
Shocks Front	Good Condition	
Shock Mountings Front	Good Condition	
Shocks Rear	Good Condition	
Stabilizer Links	Good Condition	
Wheel Bearings	Good Condition	
Bearing Hubs	Within Specification	lacksquare
Control Arms	Good Condition	
Sideshafts/Seal	No Visible Leaks	
Propshaft	Not Applicable	
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	lacksquare
Mag Wheels/Hub Caps	Good Condition	V

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	-
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	-
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	—

Ignition System		
Diagnostics	No Fault Code	_
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	_
Handling	Good Condition	V

Concluding Remarks		

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
RIAAN MEINTJIES	20-Nov-2024



