

Vehicle Diagnostic Report



Vehicle Information

Brand: renauld VIN: meebba00000701873 Plate Number: jl05sjgp

Model: KWID Mileage: Color:

Year: Capacity: Status: Unset status

Engine: Date: 10.09.2024 13:25:02

Automatic scanning results

System Name	Status/Count
01-INJECTION	Fault 1
02-AIRBAG / PRETENSIONERS	Pass No Fault
03-POWER ASSISTED STEERING	Pass No Fault
04-INSTRUMENT PANEL	Pass No Fault
05-UCH	Pass No Fault
06-RADIO	Pass No Fault

INJECTION

ID	Status	Description
<u>DF1603</u>	Memory	GEAR ENGAGEMENT SENSOR-Circuit voltage outside limits

Contact Information

Name:

Address: Pretoria Gauteng



Vehicle Diagnostic Report



Phone:	Email:
Website:	

APP Version: 1.4.8