

# All System Diagnostic Report

Pre-Scan

The Report is created by **THINKCAR**

---

## Repair Shop

Shop Name:  
Address:  
Telephone:N/A  
Email:lukas@boschgezina.co.za  
Sn:988579800333  
Time:11/21/2024 07:45:01  
Technician Name:Raymond

---

## Vehicle Information

Make:RENAULT  
Model:CAPTUR/QM3/KABIN  
VIN:VF12R141A61170480  
Displacement:G 2.4 MPI  
Odometer:148135 km  
Vehicle Software Version:V10.40

---

## Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.UCH
- 3.ABS (Anti-lock Braking System)
- 4.IC (Instrument Cluster)
- 5.AC (Air Conditioning)
- 6.TCM (Transmission Control Module)
- 7.SRS (Supplemental Inflatable Restraint System)
- 8.Parking Prox Can
- 9.Radio
- 10.Variable P.A.S
- 11.UPC
- 12.Multimedia Interface
- 13.Hands-Free Module