

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: mariska@boschgezina.co.za
Sn: 988579800333
Time: 2024-10-16 08:44:37
Technician Name: Christiaan
Order no: 1646
Service fee:
Notes:

Vehicle Information

Year: 2021
Make: USAFORD
Model: Ranger / Mazda B-Ser
VIN: AFAGXXMJ2GMB15045
Displacement: D 1.6 TCI-U2
Odometer: 95246 miles
Vehicle Software Version: V10.86

Inspection Result

The following systems are OK:

1. ABS (Anti-Lock Braking System)
2. ACM (Audio Control Module)
3. BCMII (Body Control Module)
4. FCIM (Front Controls Interface Module)
5. GWM (Gateway Module A)
6. IPC (Instrument Panel Control Module)
7. PCM (Powertrain Control Module)
8. PSCM (Power Steering Control Module)
9. RCM (Restraint Control Module)
10. RTM (Radio Transceiver Module)
11. SCCM (Steering Column Control Module)
12. TCU1 (Telematic Control Unit Module)
13. TRM (Trailer Module)