Make	VOLVO	
Model	V40 D2 MOMENTUM GEARTRONIC	
Vin	YV1MV74H0K2571859	
Engine Specifications	Diesel	
Vehicle Type	H/B	
Service Plan	N/A	

Year	2019
Km	76944
Transmission	Automatic
Colour	BLACK
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	—	Aircon Controls	Working Condition	•
Cluster	Good Condition	V	Electric Windows	Working Condition	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Not Applicable	•
Oil Filter	Not Applicable	•	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	No Visible Leaks	•	Fan Belt	No Cracks	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	•	Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable	•	Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks	~	Aircon Belt	No Cracks	•
Antifreeze	No Visible Leaks	V	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	~	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	—
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	No Visible Leaks	—

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	•
Thermostat	Within Specification	lacksquare
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	lacksquare
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	V

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	No Fault Code	lacksquare
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	—
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	▼

Transmission & Clutch		
Clutch Kit	Not Applicable	
Clutch Master	Not Applicable	-
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	—
Gearbox	Within Specification	—
Gear & Diff oil	No Visible Leaks	-
Auto Transmission	Within Specification	-
Gear Selector	Good Condition	-
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	\
Cyl Leakage Test	No Visible Leaks	•
Road Test	Within Specification	-
Handling	Within Specification	~

Concluding Remarks	
Bosch Technician	General Comments
Raymond Mncube	
NEW Technician	Date of Inspection
	15-Oct-2024



