Make	NISSAN	
Model	NP200 1.5 DCi A/C SAFETY PACK P/U S/C	
Vin	ADNUSN365U017261	0
Engine Specifications	1.5	Diesel
Vehicle Type	S/C	
Service Plan	N/A	

Year	2019
Km	119277
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Not Applicable	•
Side Mirrors / Electric	Not Applicable	•	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		119286 Km	Dip Stick	No Visible Leaks	V
Oil Filter	Renewed	•	Oil Filler Cap	Good Condition	V
Fuel/Diesel Filter	Within Specification	~	Fan Belt	Renewed	V
Air Filter	Within Specification	—	Fan belt Tensioner	Good Condition	•
Cabin Filter	Within Specification	•	Alternator Belt	Renewed	•
Spark Plugs	Not Applicable	—	Power Steering Belt	Renewed	•
Brake Fluid	Within Specification	—	Aircon Belt	Renewed	•
Antifreeze	Within Specification	lacksquare	Multi V belt	Renewed	•
Rear Main Seal	No Visible Leaks	—	Engine Mountings	Good Condition	V
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Renewed	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Renewed	•
Rear Linings	100%	•
Brake Master	Good Condition	•
Hand Brake	Renewed	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	lacksquare
Interior Fan	Good Condition	lacksquare
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Good Condition	•
Injectors	Good Condition	lacksquare
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	lacksquare

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Good Condition	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	—
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	lacksquare
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	lacksquare
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	lacksquare
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	lacksquare
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Renewed	
Mag Wheels/Hub Caps	Renewed	•

Transmission & Clutch		
Clutch Kit	Good Condition	-
Clutch Master	Good Condition	-
Clutch Slave	Good Condition	•
Clutch Cable	Not Applicable	-
Gearbox	Good Condition	-
Gear & Diff oil	Good Condition	-
Auto Transmission	Not Applicable	-
Gear Selector	Good Condition	~
Gear Linkages	Good Condition	V

Ignition System		
Diagnostics	No Fault Code	
Cyl Leakage Test	Good Condition	_
Road Test	Good Condition	-
Handling	Good Condition	~

Concluding Remarks		

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
HENDRIE	22-Oct-2024



