

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 16546

Make	PEUGEOT	
Model	BOXER L2H1 2.2 HDi	M F/C P/V
Vin	VF3YBZMFB12M7280	)8
Engine Specifications	2.2	Diesel
Vehicle Type	P/V	
Service Plan	N/A	

Year	2021
Km	18306
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	•
Cluster	Within Specification	•	Electric Windows	Within Specification	<b>•</b>

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	-

## **BOSCH VEHICLE INSPECTION**

Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	Renewed	-	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	-	Fan Belt	Within Specification	•
Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	•	Alternator Belt	Within Specification	•
Spark Plugs	Not Applicable	•	Power Steering Belt	Within Specification	•
Brake Fluid	Within Specification	•	Aircon Belt	Within Specification	•
Antifreeze	Within Specification	-	Multi V belt	Within Specification	•
Rear Main Seal	Within Specification	•	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification	•

# BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	-
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	20%	-
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Within Specification	-
Rear Drums	Not Applicable	•
Rear Linings	-Select-	-
Brake Master	Within Specification	•
Hand Brake	Within Specification	-
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	<b>•</b>
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Not Applicable	-
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Not Applicable	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Not Applicable	•
CV Joints	Not Applicable	•
CV Boots	Not Applicable	•
Shocks Front	Not Applicable	•
Shock Mountings Front	Not Applicable	•
Shocks Rear	Not Applicable	•
Stabilizer Links	Not Applicable	•
Wheel Bearings	Not Applicable	-
Bearing Hubs	Not Applicable	•
Control Arms	Not Applicable	•
Sideshafts/Seal	Not Applicable	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Not Applicable	•
Tyres & Spare	Not Applicable	•
Mag Wheels/Hub Caps	Not Applicable	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	-
Clutch Cable	Not Applicable	-
Gearbox	Not Applicable	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	Not Applicable	•
Gear Selector	Not Applicable	-
Gear Linkages	Not Applicable	•

Ignition System		
Diagnostics	Not Applicable	-
Cyl Leakage Test	Not Applicable	•
Road Test	Not Applicable	•
Handling	Not Applicable	•

#### **Concluding Remarks**

### Bosch Technician

**NEW Technician** 

-Select-

## General Comments

Date of Inspection



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

